

Fig.1
(Prior Art)




Fig. 2




Fig.3




Fig.4a




Fig.4b




Fig.5a




Fig.5b




Fig.6a

FUSE-CUT		FUSE-CONNECTED	
cut	cutb	cut	cutb
H	L	L	H

Fig.6b




Fig.7




Fig.8




Fig.9a




Fig.9b




Fig.9c




Fig.10a




Fig.10b




Fig.10c